
# St Marys site-wide Site Audit Statement CHK001/1 issued on 7/6/1999



# NSW Environment Protection Authority SITE AUDIT STATEMENT (SAS)

Site Audit Statement No.: CHK001/1

Site Auditor (accredited under NSW Contaminated Land Management Act 1997):

Name: Christopher H Kidd

Company: HLA-Envirosciences Pty Limited

Address: 55-65 Grandview Street, Pymble, NSW

Postcode: 2076

Phone: (02) 9988 4422

Fax: (02) 9988 4441

#### Site Details

ADI St. Marys Property - excluding Eastern Sector, QEL, Site 6 and Site 23, buildings and

concrete stockpile.

Address: Forrester Road, St. Marvs

Postcode: 2760

Lot and DP Number:

Lot 2 in DP803832

Lot 2 and 3 in DP223888 (part of)

Lot 3 in DP789196 Lot 3 in DP598653

(see attached map for excluded areas)

Local Government Area:

Penrith and Blacktown

#### Site Audit requested by:

Name: Mr P Newton

Company: Department of Urban Affairs and

Planning

Address:

Sydney Region West Level 8, Signature Tower 2-10 Wentworth Street Parramatta NSW 2150

Phone: (02) 9895 7142 - Fax: (02) 9895 6270

Name of contact person (if different from above:

Consultancy(ies) who conducted the site investigation(s) and/or remediation:

ADI Limited

Chemical and Explosives Ordnance

Investigations, Remediation and Validation 1990 -

1999

Mackie Martin & Associates


Groundwater Investigations, 1991

#### Title(s) of Report(s) reviewed:

- Historical Report St Marys Property, ADI Limited, 1996;
- Validation Report for the Western Sector, ADI St Marys Facility, ADI Limited November 1994;
- Validation Report for the North Western Sector of the ADI St Marys Facility, Report No. 498800, ADI Limited 1995;
- Validation Report for the Southern Sector West of the ADI St Marys Property, Report No. 498810, ADI Limited 1996;

1-3

P:\J JOBS\J1200 to J1249\J1219\Site Audit Statements abede.doc



- Validation Report for the Southern Sector East of the St Marys Property, Report No. 498810, ADI Limited 1996;
- Validation Report for the Northern Sector of the ADI St Marys Property, Report No. 498820, ADI Limited 1996;
- Validation Report for the Cental Sector East of the ADI St Marys Property, Report No. 498840, ADI Limited 1997;
- Validation Report for the Central Sector West of the ADI St Marys Property, Report No. 498840, ADI Limited 1996;
- Validation Report for the North Eastern Sector of the ADI St Marys Property, Report No. 498850, ADI Limited 1996;
- QA/Verification Survey Results, ADI St Marys Property, Report No. PG980323da ADI Limited, 1999.

### Other Information reviewed:

- Site Investigation Report of St Marys Facility Ammunition and Missiles Division, Volume 4 - Discussions and Conclusions, ADL June 1991.
- 2. Remediation Action Plan for the Northern Sector, ADI St Marys Facility, Report No. 498820, ADI Limited 1996;
- 3. Remediation Action Plan for Central Eastern Sector, ADI St Marys Facility, Report No. 498840, ADI Limited 1996;
- 4. Remediation Action Plan for the Eastern Sector of the ADI St Marys Property, Report No. 498830, ADI Limited 1996;
- Stage I Decontamination Audit, ADI St Marys CMPS&F, 1997.

# Summary Site Audit Report Title:


Stage 2 Decontamination Audit Report for ADI Site, St Marys.

I have completed a site audit (as defined in the Contaminated Land Management Act 1997) and reviewed the reports and information referred to above with due regard to relevant laws and guidelines. I certify that the site (tick all appropriate boxes)

(a) is suitable for the following use(s):

- ✓ residential, including substantial vegetable garden and poultry;
- 🖵 residential, including substantial vegetable garden, excluding poultry; பட்ட
- and residential with accessible soil, including garden (minimal home grown produce sontributing less than 10% fruit and vegetable intake), excluding poultry;
- √ residential with minimal opportunity for soil access including units;
- √ daycare centre, preschool, primary school;
- ✓ secondary school;
- ✓ park, recreational open space, playing field;
- ✓ commercial/industrial use;
- Other

Line



### subject to

#### ✓ Conditions

- Excludes Eastern Sector, QEL, Site 6 and Site 23 which are covered by separate site audit statements, namely CHK001/2, CHK001/3, CHK001/4 and CHK001/5.
- Excludes areas not yet investigated including the footprint of original buildings, car
  parks and roads, mainly around former Administration Centre Buildings
  CHK001/6) and the concrete stockpile in Central Sector West. (Stockpile
  CHK001/7)
- 3. An appropriate management plan, including procedures for the safe handling and disposal of any items of ordnance that may be found during earthworks, should be lodged prior to the commencement of development earthworks. This plan should be similar to the "Remnant Contamination Management Plan" submitted by ADI (see Appendix E of the Site Audit Report).

(b) is not suitable for any beneficial use due to risk of harm from contamination	Winit
(comments):	

I am accredited by the NSW Environment Protection Authority under the Contaminated Land Management Act, 1997 as a site auditor (Accreditation No. 9813).

## I Certify that:


- (a) I have personally examined and am familiar with the information contained in this statement, including the reports and information referred to in this statement, and
- (b) this statement is to the best of my knowledge, true, accurate and complete, and
- (c) on the basis of my inquiries made to those individuals immediately responsible for making the reports, and obtaining the information, referred to in this statement, those reports and that information are, to the best of my knowledge, true, accurate and complete.

I am aware that there are penalties for wilfully submitting false, inaccurate or incomplete information.

Signed: Oricidal

Date: 7/6/99

3-3



Document Set ID: 6020962 Version: 1, Version Date: 01/07/2014