

GEOTECHNICAL & ENVIRONMENTAL SERVICES

PRELIMINARY SITE INVESTIGATION



Prepared For: Architecture Design Studio (NSW) Pty Ltd Address: 118-120 Station Street Penrith, NSW, 2750 Job No: AG-533_1 Date: 18-09-20

Australian Geotechnical Pty Ltd ABN 27 611 088 192

Document Set ID: 9397752 Version: 1, Version Date: 01/12/2020

TABLE OF CONTENTS

Description

Page No

Table of Contents	
Executive Summary	3
1.0 Introduction	5
1.1 Overview	5
2.0 Scope of Work	5
3.0 Site Description and Aesthetics	6
4.0 Site Geology and Hydrogeology	7
5.0 Acid Sulfate Soil	7
6.0 Site History	7
6.1 Previous Land Use and Review	7
6.2 Historic Land Titles	8
6.3 Search of Contaminated Land Register	8
6.4 Search of POEO Register	8
6.5 Safe Work NSW Records	8
6.6 Product Spill and Loss History	9
6.7 Section 149 Certificate	9
7.0 Site Condition and Surrounding Environment	9
8.0 Areas of Environmental Concern	9
9.0 Conceptual Site Model	10
10.0 Data Gaps	11
11.0 Conclusion and Recommendations	11

References

Limitations Appendices

List of Abbreviations

A list of the common abbreviations used throughout this report is provided below.

ACM AEC AGST AHD bgs CSM BTEX B(a)P CCA	 Asbestos Containing Material Area of Environmental Concern Above Ground Storage Tank Australian Height Datum Below ground surface Conceptual site model Benzene, toluene, ethylbenzene and xylenes Benzo(a)pyrene Copper Chromate Arsenate
COC	- Contaminants of Concern
AG	- Australian Geotechnical Pty Ltd
DEC	- NSW Department of Environment and Conservation
	- NSW Department of Environment, Climate Change and Water
DQI DQOs	 Data quality indicator Data Quality Objectives
DQOS	- NSW Department of Water and Energy
EPA	- NSW Environment Protection Authority
ESA	- Environmental Site Assessment
ha	- Hectare
HIL	- Health based investigation level
LOR	- Limit of Reporting
OEH	- Office of Environment and Heritage
PAHs	- Polycyclic aromatic hydrocarbons
PID	- Photo-ionisation Detector
PCB	- Polychlorinated Biphenyl
PQL	- Practical Quantitation Limit
QA/QC	- Quality Assurance/Quality Control
RPD	- Relative Percentage Difference
SAQP	- Sampling, Analysis and Quality Plan
TRH	- Total Recoverable Hydrocarbons (previously Total Petroleum Hydrocarbons)
TSS	- Total Suspended Solids
UST	- Underground Storage Tank
VOC	- Volatile Organic Compound

Executive Summary

This executive summary presents a synopsis of the Preliminary Site Investigation (PSI) Assessment for 118-120 Station Street Penrith, NSW, 2750.

The object of the PSI was to ascertain whether the site presents a risk to human health and/or the environment arising from any past/present activities at the site or neighboring properties. The scope of work included a documentary review together with preparation of this report.

A PSI was requested by Architecture Design Studio (NSW) Pty Ltd to determine the potential for on-site contamination. This report shall provide a preliminary assessment of any site contamination and, if required, provide a basis for a more detailed investigation. At the time of the inspection (14th September 2020), the appeared was a vacant block of land. It is understood that the proposed development for the site will comprise construction of a six storey residential unit block with 19 units in conjunction with excavation of two (2) levels of basement car parking. The lower basement floor level will be excavated to approximate RL 22.5m.

Based on historical information reviewed, the site has historically been used historically for residential purposes. The potential for the site to be contaminated from on-site sources and off-site sources was considered by Australian Geotechnical Pty Ltd (AG). Based on the findings of our site inspection and site history review actual or potential contamination sources were identified as low in relation to the proposed development for the subject site.

The following areas were identified in the conceptual site model as areas of environmental concern;

- Building degradation from previous site structures, which includes potential heavy metal and asbestos contamination;
- Importation of fill material that may contain various contaminants; and
- Car park areas where leaks and spills from cars may have occurred.

Based on the finding of this investigation it is considered that the risk to human health and the environment associated with soil and groundwater contamination is low in relation to the proposed development for the subject site. The site can be made suitable for the proposed development, subject to the following recommendations:

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

- Preparation of a targeted Environmental Site Assessment in order to address data gaps identified in section 10.0 of this report, this can be undertaken in conjunction with a waste classification for off-site disposal of spoil excavated for the proposed basement car parking area. Any soils requiring removal from the site must initially be classified in accordance with the NSW Waste Classification Guidelines, Part 1 dated 2014. The classification of spoil must be undertaken prior to occupation of the site with construction, excavation and site workers; and
- Address data gaps, if required.

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

1.0 INTRODUCTION

1.1 Overview

AG have undertaken a Preliminary Site Investigation (PSI) with as requested by Architecture Design Studio (NSW) Pty Ltd at the site; 118-120 Station Street Penrith, NSW, 2750. This report has been prepared to determine assess the suitability of the site for development based on its current condition and the findings of this investigation.

2.0 SCOPE OF WORK

This PSI has been prepared in general accordance with the following regulatory framework:

- NSW Environment Protection Authority (EPA) "Guidelines for Consultants Reporting on Contaminated Sites" (2020);
- NEPM (2013), Schedule B2 Guideline on Site Characterisation;
- State Environment Protection Policy 55 (SEPP 55). Remediation of Land Under the Environmental Planning and Assessment Act 1997;
- National Environment Protection (Assessment of Site Contamination) Measure National Environmental Protection Council 2013.

The scope of works required to complete the PSI are as follows:

- Review of the current site conditions based on a site inspection, including the location of sewers, drains, spills, patches of discoloured vegetation and bare patches of soil, etc.
- Review of available information, including previous environmental and geotechnical investigations, past and current title information, aerial photographs, geological/topographical/hydrogeological data and mapping, soil landscapes, desktop search, EPA and council records, anecdotal evidence, site survey and site records;
- Construct a Conceptual Site Model (CSM) in order to validate connections between potential sources of contamination, exposure pathways and receptors; and
- Recommendations for supplementary investigations or possible management strategies, should any data gaps be identified.

3.0 SITE DESCRIPTION AND AESTHETICS

The subject site is approximately rectangular in shape, legally defined as Lot 4 and Lot 5 in Deposited Plan 112466 and Lot 6 in Deposited Plan 1003862. The site is bounded by a recently constructed high density unit block to the north-east, low density residential structure to the south-east, Station Street to the north-west with Reserve Street situated to the Parramatta Road to the north, with a car park and hard stand area situated south-west of the subject site. The site measures approximately 30m along the Station Street road frontage and up to 31m across Reserve Street, encompassing a total area of 935.5m² based on the site survey.

At the time of the site inspection, the following observations were made:

- The site is vacant, no contamination was visually observed across the site.
- Vegetation was generally stripped from the site.
- There were no indicators of underground storage tanks within the site;

4.0 SITE GEOLOGY AND HYDROGEOLOGY

The Soil Landscape Series Sheet 9030ri, Scale 1:100,000, 2002, prepared by the Soil Conservation Service of NSW, indicates that the site is located within the Richmond Landscape which generally comprises of *Quaternary alluvium consisting of sand, silt and gravels derived from sandstone and shale.*

A search of the NSW Department of Primary Industries Office of Water registered groundwater bores was undertaken by AG, with a search radius of 500m around the site. Six registered recreational bores was identified within a 0.5 km radius of the site. These bores indicated that standing water level of 6m and 8m below surface level.

5.0 ACID SULFATE SOIL

To determine whether there is a potential for acid sulfate soils to be present at the site, reference was made to the NSW Office of Environment and Heritage (OEH), eSPADE map viewer. A review of the map indicated that the site is in an area of "No known occurrence" in regards to Acid Sulfate Soil.

6.0 SITE HISTORY

In order to ascertain the site history, a documentary review of past and present land use at the subject site and the surrounding area has been undertaken as follows.

6.1 **Previous Land Use and Review of Historical Photographs**

Aerial Photographs were obtained by this office from the NSW Department of Lands Office. The aerial photographs were reviewed to assess the likely past uses of the site with the findings summarised below;

1943 – The site appears to be vacant. Some residential development can be seen around the subject site. Reserve and Station Street has been formed;

1961- Two (2) low density residential structures appear to occupy the north-western portion of site. A detached garage can be seen adjacent to the residential structures;

1970– Generally the same as 1961. An additional detached structure (garage) can be seen within the southern portion of site, additional vegetation growth can be observed;

1994 – The image isn't clear, however no change can be seen across the site;

2009 – No change from the 1994 image;

Current – The site is vacant, it is understood that structures occupying the site were demolished in 2018.

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

6.2 Historic land titles

A review of historical transactions and titles held at the NSW Department of Lands offices was conducted by AG to identify the land owners and potential land uses with regards to possible contamination. The results of the title searches are summarised below in table 1 below;

Table 1 – Land Title Transactions Lot 4 and 5 in Deposited Plan 112466

Date of acquisition and held term	Registed proprietor(s) & occupations where available
2018 to Current	James Ashley Aitken and David John
	Reeves
1992 to 2018	Terence Sean McCabe
1980 to 1992	Andrejs Baltins
Prior to 1980	Commonwealth Bank of Australia

Table 2 – Land Title Transactions Lot 6 in Deposited Plan 1003862

Date of acquisition and held term	Registed proprietor(s) & occupations where available
2018 to Current	James Ashley Aitken and David John Reeves
2003 to 2018	James Ashley Aitken and David John Reeves, James Walter Aitken, Marlene Ruth Aitken
1999 to 2003	Doreen Marjorie Milsom and Ronald William Milsom

6.3 Search of Contaminated Land Management Register (NSW EPA)

A summary of the area can be found. No notices have been issued to the subject site. Furthermore, the listed sites on the register are situated at such a distance (greater than 200m), that they are not believed to have provided a potential contamination risk to the subject property.

6.4 Search of Protection of the Environment Operations Public Register (POEO) of Licensed and Delicensed Premises

A search of the POEO public register of licensed and delicensed premises (DECC) indicated that no licensed or delicensed premises were located within the immediate surrounding area of the site (within 200m).

6.5 Safe Work NSW Records

At the time of reporting, this office had not been given authorisation to request a search of the Stored Chemical Information Database (SCID) for licenses to keep dangerous goods at the site from Safe Work NSW.

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

6.6 **Product Spill & Loss History**

No external information was provided for any product spill and loss. However, based on the site inspection, no major signs chemical staining were observed.

6.7 Section 149 Certificates

At the time of reporting, this office could not access The Planning Certificate – Section 149 of the Environmental Planning & Assessment Act 1979.

7.0 SITE CONDITION AND SURROUNDING ENVIRONMENT

A site investigation was conducted on 14th September 2020. The field observations are summarized in table 3 below:

Parameter	Observation
Visible observations on	No visible contamination observed. No odours were
soil contamination	documented.
Presence of drums, fill or	None observed. No visible indicators of underground fuel
waste materials	tanks (bowsers or venting pipes).
Presence of fill	Approximately 700mm of fill was observed based on
	geotechnical report
Flood potential	Not evident.
Relevant sensitive	None observed
environments	
Asbestos	No asbestos was not observed visually

Table 3 – Summary of Field Observations

8.0 AREAS OF ENVIRONMENTAL CONCERN

Based on historical information reviewed, the site has been utilised for residential purposes. The site was vacant until receiving residential structures between 1943 and 1961 in conjunction with detached garage structures. Aerial imagery indicates that the residential structures were demolished sometime in 2018.

The potential for the site to be contaminated from on-site sources and off-site sources was considered by AG. Based on the findings of our site inspection and site history review actual or potential contamination sources were identified as low. Based on the site inspection, site history, previous reporting and review of available information from the desktop study, the potential Areas of Environmental Concern (AEC) and their associated Contaminants of Concern (CoCs) for the site were identified. These are summarised in the conceptual site model in table 4 below;

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

Potential AEC	Potentially contaminating activity	Likelihood of Site Impact	Potential CoCs	Comments
Entire Site	Importation of fill material from unknown origin.	High	Metals, TPH, BTEX, PAH, OCP, OPP, PCB, Asbestos, Phenols, Cyanide	Based on observations and site topography, the presence of imported fill material is likely to be around 500mm to 700mm thick
Location of previous residential structures and garage	Building degradation	Low	Heavy metals & Asbestos	Based on the site survey prepared by Matthew Freeburn, drawing 36 206DE dated 13-12-2017, the structures were constructed using fibro cement sheeting. A HAZMAT report is required to confirm absence/presence of hazardous material prior to demolition in 2018
Car Parking Areas	Leaks from vehicles	Low	TPH, Metal, BTEX, PAH	Historical car parking surfaces were generally in good condition.

Table 4 – Contaminants of Concern

9.0 CONCEPTUAL SITE MODEL

In accordance with NEPM (2013), *Schedule B2 – Guideline on Site Characterisation* and to assist in collecting data for the site. The Conceptual Site Model (CSM) detailed in table 5 below considers the potential risks associated with the plausible pollution linkages between the following features:

- Potential human receptors that may be impacted by site contamination are current and future occupants at the site, excavation/construction and maintenance workers during demolition and construction phase of the project and the general public within close proximity to the site;
- Potential sources of contamination, location and the contaminants of concern identified are presented in Section 8.0. Only potential areas of concern with a likelihood of site impact rating of low to high are included;
- Potential exposure pathways; and

¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.

• Whether the linkage between each source-pathway-receptor is complete, based on our current site inspection, historical information presented and proposed future site condition.

Potential Sources	Potential Receptor	Exposure Pathway	Complete Linkages	Risk	Justification
Building degradation	Site Users, General	Dermal Contact,	Yes (current)	Low	Direct contact with soil outside
Leaks from vehicles	Public, Construction Workers	Inhalation of Dust.			of hardstand areas in courtyard areas
Uncontrolled	Wonters		Yes (future)	Low	If present, impacted soil will
Fill Material			(luture)		be removed from site, however
					there will remain soil in future
					areas with direct soil access.

Table 5 – Conceptual Site Model

10.0 DATA GAPS

Based on the CSM derived for the site, the following data gaps were identified, which may be considered to warrant closure by further limited investigation:

- Whether contamination has occurred at the carparking areas;
- The quality of fill material;
- Whether contamination has occurred from degradation of structures;
- The presence and quality of groundwater; and
- Council and Safe Work NSW searches.

11.0 CONCLUSION AND RECOMMENDATIONS

Based on the finding of this investigation it is considered that the risk to human health and the environment associated with soil and groundwater contamination is low in relation to the proposed development for the subject site. The site can be made suitable for the proposed development, subject to the following recommendations.

• Preparation of a targeted Environmental Site Assessment in order to address data gaps identified in section 10.0 of this report, this can be undertaken in conjunction with a waste classification for off-site disposal of spoil excavated for the proposed basement car parking area. Any soils requiring removal from the site must initially be classified in accordance with the NSW Waste Classification Guidelines, Part 1 dated 2014. The classification of spoil must be undertaken prior to occupation of the site with construction, excavation and site workers; and

• Address data gaps, if required.

Should you have any queries, please do not hesitate to contact the undersigned.

For and on behalf of Australian Geotechnical Pty Ltd

N. Smith Principal

References

- Contaminated Sites Guidelines for Consultants Reporting on Contaminated Sites. NSW Environment Protection Authority (EPA) 2020.
- State Environment Protection Policy 55 (SEPP 55). Remediation of Land Under the Environmental Planning and Assessment Act 1997;
- Contaminated Sites Sampling Design Guidelines. NSW Environment Protection Authority (EPA) 1995
- National Environment Protection (Assessment of Site Contamination) Measure National Environmental Protection Council 2013.
- The 1:250,000 scale Geological Series Map of the Penrith
- NSW EPA "Guidelines on the Duty to Report Contamination under the Contaminated Land Management Act 1997" (2009). NSW Environment Protection Authority, Sydney;
- ANZECC/NHMRC (1992) "Australian and New Zealand Guidelines for the Assessment and Management of Contaminated Sites". Australian and New Zealand Environment and Conservation Council and the National Health and Medical Research Council, Canberra;
- NSW DEC, "Guidelines for the Assessment and Management of Groundwater Contamination" (March 2007);
- SIX Maps Viewer

LIMITATIONS

It should be noted that these materials were visually inspected and no laboratory analysis was conducted. If materials or conditions are encountered other than those that have been described, further assessment will be required. At the time of our inspection, no information was given on the acceptance criteria or chemical testing requirements at the recipient site. If this information becomes available, we can review this and organise the appropriate testing required at your request.

Australian Geotechnical Pty Ltd (AG) has prepared this report for Architecture Design Studio (NSW) Pty Ltd. The report is provided for the exclusive use of Architecture Design Studio (NSW) Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. Any party so relying upon this report beyond its exclusive use and purpose as stated above, and without the express written consent of AG, does so entirely at its own risk and without recourse to AG for any loss or damage. In preparing this report AG has necessarily relied upon information provided by the client and/or their agents.

Where data has been supplied by the client or a third party, it is assumed that the information is correct unless otherwise stated. No responsibility is accepted by AG for incomplete or inaccurate data supplied by others

AG's contamination assessment is necessarily based on the result of a desktop site historical search and site inspection only and did not include surface or subsurface sample screening and/or chemical testing. AG's advice is based upon the conditions encountered during this investigation. The accuracy of the advice provided by AG in this report may be affected by undetected variations in ground conditions across the site. It is noted that this assessment does not constitute a hazardous material building assessment. The advice may also be limited by budget constraints imposed by others or by site accessibility.


This report must be read in conjunction with all of the attached and should be kept in its entirety without separation of individual pages or sections. AG cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion stated in this report. This report, or sections from this report, should not be used as part of a specification for a project, without review and agreement by AG. This is because this report has been written as advice and opinion rather than instructions for construction.

The contents of this report do not constitute formal design components such as are required, by the Health and Safety Legislation and Regulations, to be included in a Safety Report specifying the hazards likely to be encountered during construction and the controls required to mitigate risk. This design process requires risk assessment to be undertaken, with such assessment being dependent upon factors relating to likelihood of occurrence and consequences of damage to property and to life. This, in turn, requires project data and analysis presently beyond the knowledge and project role respectively of AG. AG may be able, however, to assist the client in carrying out a risk assessment of potential hazards contained in this report, as an extension to the current scope of works, if so requested, and provided that suitable additional information is made available to AG. Any such risk assessment would, however, be necessarily restricted to the environmental components set out in this report and to their application by the project designers to project design, construction, maintenance and demolition.


¹¹⁸⁻¹²⁰ Station Street Penrith, NSW, 2750.


SUPPORTING DOCUMENTATION
















Indicative Plans


Issue Date:	21/09/2020	DIAL BEFORE
Location:	118 Station Street, Penrith, NSW, 2750	YOU DIG www.1100.com.au

1	









Emergency Contacts

You must immediately report any damage to **nbn™** network that you are/become aware of. Notification may be by telephone - 1800 626 329.


MIXED USE DEVELOPMENT 118 - 120 | STATION STREET | PENRITH

UNIT SCHEDULE														
Apartment No:	No of Bedrooms	Area (m2)	Adaptable	Cross Ventilation	Kitchen Ventilation	09.00	10.00	11.00	12.00	13.00	14.00	15.00	Total Solar Access	Total Storage
01-01	3 BEDROOM	103.32	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
01-02	2 BEDROOM	75.00	NO	YES	NO	1	1	1	1	1	1	1	6 HRS	0.00
01-03	2 BEDROOM	76.76	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
01-04	3 BEDROOM	102.99	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
02-01	3 BEDROOM	103.32	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
02-02	2 BEDROOM	75.00	NO	YES	NO	1	1	1	1	1	1	1	6 HRS	0.00
02-03	2 BEDROOM	76.76	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
02-04	3 BEDROOM	102.99	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
03-01	3 BEDROOM	103.32	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
03-02	2 BEDROOM	75.00	NO	YES	NO	1	1	1	1	1	1	1	6 HRS	0.00
03-03	2 BEDROOM	76.76	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
03-04	3 BEDROOM	102.99	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
04-02	2 BEDROOM	75.21	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
04-02	2 BEDROOM	75.21	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
04-02	2 BEDROOM	83.32	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
04-02	2 BEDROOM	83.32	NO	YES	NO	0	1	1	1	1	1	1	5 HRS	0.00
04-03	3 BEDROOM	95.10	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
04-03	3 BEDROOM	95.10	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
04-03	3 BEDROOM	95.10	NO	YES	NO	1	1	1	1	0	0	0	3 HRS	0.00
19		1,676.57 m ²												0.00

Apartment Type Count							
APARTMENT							
	2 BEDROOM	10					
	3 BEDROOM	9					
		19					

Area Schedule - GFA						
Zone Type Area						
GFA - Fifth Floor	289.31					
GFA - First Floor	391.44					
GFA - Fourth Floor	391.44					
GFA - Ground Floor	376.49					
GFA - Second Floor	391.44					
GFA - Third Floor	391.44					
	2,231.56 m ²					

	SCHEDULE OF AREAS
ADDRESS	118 - 120 STATION STREET PENRITH NSW 2750 Australia
LOT AND DP	LOTS 4 & 5 IN DP 112466 & LOT 6 DP 1003862
SITE AREA	935.5 m2



	5 10m		
	Duu Bulu Annadanad Bu	GENERAL NOTES: 1. ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. PREFERNCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED MEASURMENTS. 2. ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY. 3. INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE AND PROPER FUNCTIONING OF THE PROJECT. DO NOT ALTER ANY ASPECT WITHOUT REFERENCE TO THE ARCHITECT. 4. READ THIS DRAWING IN CONJUNCTION WITH RELEVANT CONSULTANT DRAWINGS AND SPECIFICATIONS.	CONSTRUCTION COLOR OF ADSTRUCT, AUSTRUCTAR STANDARDS, CODES AND ALL RELEVANT CONDITIONS BY-LAW 7. THE BUILDING / MANUFACTURER SHALL CHECK AND VERIFY ALL DIMENSIONS, RL GROUNDLINES AND CONSTRUCTION METHODS I COMMENCEMENT OF WORK. 8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL COUI 9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE U
Rev Date Amendment By	Rev Date Amendment By	DRAWINGS AND SPECIFICATIONS.	THE PURPOSE FOR WHICH IT IS ISSUED


450 9.95 m² - __ - __ - __ - __ - __ - __ - __ /



Structural Engineer: #Structural Engineer	
Mechanical Services: #Mechanical Engineer	
Electrical Services: #Electrical Engineer	

Hydraulic Services: #Hydraulic Engineer Fire Services: #Fire Engineer BCA and Access Consultant: #BCA & Access Consultant

Principal Certifying Authority: #Principal Certifying Authority Landscape Architect: #Landscape Architect Acoustic Engineer: #Acoustic Engineer





Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia




BASEMENT PLAN Drawing No **1101**

Date A1 Scale A3 Scale 24/07/2020 1:100 50%

Checked

Revision



10m

				5. INFORM THE ARCHITECT OF ANY DISCREPANCIES
		1	 ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. PREFERNCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED 	 THE WORK IS TO BE COMPLETED IN ACCORDANCE WITH THE NATION CONSTRUCTION CODE OF AUSTRALIA, AUSTRALIAN STANDARDS, S CODES AND ALL RELEVANT CONDITIONS BY-LAW
			MEASURMENTS. 2. ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY. 3. INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE	7. THE BUILDING / MANUFACTURER SHALL CHECK AND VERIFY ALL DIMENSIONS, RL GROUNDLINES AND CONSTRUCTION METHODS PF
			AND PROPER FUNCTIONING OF THE PROJECT. DO NOT ALTER ANY ASPECT WITHOUT REFERENCE TO THE ARCHITECT.	COMMENCEMENT OF WORK. 8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR T WATERBOARD FOR APPROVAL AS REQUIRED BY THE LOCAL COUNT
Rev Date	Amendment By	/ Rev Date Amendment By	 READ THIS DRAWING IN CONJUNCTION WITH RELEVANT CONSULTANT DRAWINGS AND SPECIFICATIONS. 	9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE US THE PURPOSE FOR WHICH IT IS ISSUED

Document Set ID: 9397752 Version: 1, Version Date: 01/12/2020






Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia




Drawing Title UPPER BASEMENT FLOOR BASEMENT PLAN Drawing No **1102** Date A1 Scale A3 Scale 24/07/2020 1:100 50%


Revision



Rev Date Amendment

By Rev Date Amendment





4105

2 4105

+27,500 $\langle \rangle \rangle$ **`**~ ı ___



Structural Engineer: #Structural Engineer Mechanical Services: #Mechanical Engineer Electrical Services: #Electrical Engineer

Hydraulic Services: #Hydraulic Engineer Fire Services: #Fire Engineer BCA and Access Consultant: #BCA & Access Consultant

Principal Certifying Authority: #Principal Certifying Authority Landscape Architect: #Landscape Architect Acoustic Engineer: #Acoustic Engineer




PENRITH NSW 2750 Australia



Drawing Title GROUND FLOOR GROUND FLOOR / PODIUM PLAN Drawing No **1202** Date A1 Scale A3 Scale 24/07/2020 1:100 50%

Revision Checked






Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia



Drawing Title FIRST FLOOR UPPER FLOOR PLAN Drawing No **1301** Date A1 Scale A3 Scale 24/07/2020 1:100 50%


Revision



	5 10m		
		1. ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. PREFERNCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED MEASURMENTS. 2. ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY. 3. INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE AND PROPER FUNCTIONING OF THE PROJECT. DO NOT ALTER ANY ASPECT WITHOUT REFERENCE TO THE ARCHITECT. 4. READ THIS DRAWING IN CONJUNCTION WITH RELEVANT CONSULTANT	 INFORM THE ARCHITECT OF ANY DISCREPANCIES THE WORK IS TO BE COMPLETED IN ACCORDANCE WITH THE CONSTRUCTION CODE OF AUSTRALIA, AUSTRALIAN STANDAR CODES AND ALL RELEVANT CONDITIONS BY-LAW THE BUILDING / MANUFACTURER SHALL CHECK AND VERIFY A DIMENSIONS, RL GROUNDLINES AND CONSTRUCTION METHO COMMENCEMENT OF WORK. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIE WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL OF 9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY
Rev Date Amendment By	y Rev Date Amendment By	DRAWINGS AND SPECIFICATIONS.	THE PURPOSE FOR WHICH IT IS ISSUED

Document Set ID: 9397752

Version: 1, Version Date: 01/12/2020





Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia




Drawing Title SECOND FLOOR UPPER FLOOR PLAN Drawing No **1302**

Revision

Checked

Date A1 Scale A3 Scale 24/07/2020 1:100 50%



		1
		1

	GENERAL NOTES:	5. INFORM THE ARCHITECT OF ANY DISCREPANCIES 6. THE WORK IS TO BE COMPLETED IN ACCORDANCE WITH THE NATIONAL
	1. ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. PREFERNCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED	CONSTRUCTION CODE OF AUSTRALIA, AUSTRALIAN STANDARDS, SAA CODES AND ALL RELEVANT CONDITIONS BY-LAW
	MEASURMENTS. 2. ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY.	7. THE BUILDING / MANUFACTURER SHALL CHECK AND VERIFY ALL
	3. INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE	DIMENSIONS, RL GROUNDLINES AND CONSTRUCTION METHODS PRIOR TO COMMENCEMENT OF WORK.
	AND PROPER FUNCTIONING OF THE PROJECT. DO NOT ALTER ANY ASPECT WITHOUT REFERENCE TO THE ARCHITECT.	8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR TO THE WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL COUNCIL.
Rev Date Amendment Bv	 4. READ THIS DRAWING IN CONJUNCTION WITH RELEVANT CONSULTANT DRAWINGS AND SPECIFICATIONS.	9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT IS ISSUED

Structural Engineer: #Structural Engineer Hydraulic Services: #Hydraulic Engineer Mechanical Services: #Mechanical Engineer Fire Services: #Fire Engineer NSW Nominated Architect Pavlo Doroch 9170 BCA and Access Consultant: #BCA & Access Consultant Electrical Services: #Electrical Engineer

Principal Certifying Authority: #Principal Certifying Authority Landscape Architect: #Landscape Architect Acoustic Engineer: #Acoustic Engineer




Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia



Drawing Title THIRD FLOOR UPPER FLOOR PLAN Drawing No 1303 Date A1 Scale A3 Scale 24/07/2020 1:100 50%

Revision



0 1 2

10m

			_			GENERAL NOTES:	5. INFORM THE ARCHITECT OF ANY DISCREPANCIES
	Rev Date	Amendment B	y Rev D	ate Ameno	dment By	1. ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. PREFERNCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED MEASURMENTS. 2. ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY. 3. INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE AND PROPER FUNCTIONING OF THE PROJECT. DO NOT ALTER ANY ASPECT WITHOUT REFERENCE TO THE ARCHITECT. 4. DEAD SUPER DIMENSIONED WITH OUT DIMENSIONED WITHOUT DATE.	CODES AND ALL RELEVANT CONDITIONS BY LAW T THE BUILDING / MANUFACTURER SHALL CHECK AND VERIEY ALL
nent Se	et ID: 9397752						

Document Set ID: 9397752 Version: 1, Version Date: 01/12/2020



4105 30.445m

4105




Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia



Drawing Title FOURTH FLOOR UPPER FLOOR PLAN Drawing No **1304** Date A1 Scale A3 Scale 24/07/2020 1:100 50%

Revision



0 1 2 5 10m		
	Structural Engineer: 5. INFORM THE ARCHITECT OF ANY DISCREPANCIES ALL DIMENSIONS AND SIZES ARE IN MILLIMETRES. DO NOT SCALE DRAWINGS. 6. THE WORK IS TO BE COMPLETED IN ACCORDANCE WITH THE NATIONAL CONSTRUCTION CODE OF AUSTRALIA, AUSTRALIA, AUSTRALIA, AUSTRALIA, AUSTRALIA, AUSTRALIA, AUSTRALIA, AUSTRALIA, STANDARDS, SAA PREFERENCES OF DIMENSIONED MESURMENT TO BE TAKEN OVER SCALED #Hydraulic Engineer #Hydraulic Engineer #Hydraulic Engineer	Principal Certifying Authority: #Principal Certifying Authorit
	MEASURMENTS. . ALL WALL THICKNESSES DIMENSIONED OR NOTED ARE NOMINAL SIZES ONLY. . INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE INFORMATION INDICATED IN THIS DOCUMENT MAY BE CRUCIAL TO THE SAFE ABN: 90 616 216 196 Mechanical Engineer ABN: 90 616 216 196	Landscape Architect: #Landscape Architect
	AND PROPER FONCTIONING OF THE PROJECT TO THE ARCHITECT. WITHOUT REFERENCE TO THE ARCHITECT. READ THIS DRAWING IN CONJUNCTION WITH RELEVANT CONSULTANT DRAWINGS AND SPECIFICATIONS. 8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR TO THE WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL COUNCIL. 9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT IS ISSUED 8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR TO THE WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL COUNCIL. 9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT IS ISSUED 8. A COPY OF THIS PLAN IS TO BE SUBMITTED BY THE PROPRIETOR TO THE WATERBOARD FOR APPROVALAS REQUIRED BY THE LOCAL COUNCIL. 9. THIS DRAWING IS PROTECTED BY COPYRIGHT. IT MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT IS ISSUED	



Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia



Drawing Title FIFTH FLOOR UPPER FLOOR PLAN Drawing No 1305 Date A1 Scale A3 Scale 24/07/2020 1:100 50%

Revision



Document Set ID: 9397752

Version: 1, Version Date: 01/12/2020

ional Saa				Structural Engineer: #Structural Engineer	Hydraulic Services: #Hydraulic Engineer	Principal Certifying Authorit #Principal Certifying Auth
PRIOR TO			ABN: 90 616 216 196	Mechanical Services: #Mechanical Engineer	Fire Services: #Fire Engineer	Landscape Architect: #Landscape Architect
to the ICIL. Sed for			NSW Nominated Architect	Electrical Services: #Electrical Engineer	BCA and Access Consultant: #BCA & Access Consultant	Acoustic Engineer: #Acoustic Engineer

50.700	
Roof	

+47.600 Level 6

+44.500

+41.400 +38.300 Level 3

0

ш

+35.200 Level 2

+32.100

+28.100 Ground Floor



Jim Aitken Partners Address
118 - 120 STATION STREET PENRITH NSW 2750 Australia



Drawing Title North & South Elevations GA ELEVATION Drawing No **1501**
 Date
 A1 Scale
 A3 Scale


 24/07/2020
 1:100
 50%


Checked

Revision



AAL A DR TO THE DFOR ABN: 90 6 NSW Nomin Pavlo Doroc	Structural Engineer: #Structural Engineer Mechanical Services: #Mechanical Engineer Electrical Services: #Electrical Engineer	Hydraulic Services: #Hydraulic Engineer Fire Services: #Fire Engineer BCA and Access Consultant: #BCA & Access Consultant	Principal Certifying Authority: #Principal Certifying Authority: Landscape Architect: #Landscape Architect Acoustic Engineer: #Acoustic Engineer





24M MAX HEIGHT 24M MAX HEIGHT +50,700 7 Roof COMMON OPEN SPACE LOBBY LDRY LOBBY ___ · __ · __ 4 Level LOBBY LOBBY +35,200 2 Level 2 LOBBY +32,100 1 Level 1 ____ · ____ Living/Dining Terrace +28,100 0 Ground Floor +25,300 I Basement 1 +22,500 2 Basement 2 Drawing Title A B Section Jim Aitken Mixed use development GA SECTION Drawing No **1602** Revision Partners

Address 118 - 120 STATION STREET PENRITH NSW 2750 Australia

Project No.

Pn_0735

 Date
 A1 Scale
 A3 Scale

 24/07/2020
 1:100
 50%

WaterNSW Work Summary

GW103048

Licence:		Licence Status:	
		Authorised Purpose(s): Intended Purpose(s): RECREATION (GROU	
Work Type:	Bore		
Work Status:			
Construct.Method:			
Owner Type:			
Commenced Date: Completion Date:	01/01/1990	Final Depth: 8.00 m Drilled Depth: 8.00 m	
Contractor Name:	(None)		
Driller:			
Assistant Driller:			
Property:		Standing Water Level 6.000	
GWMA: GW Zone:		(m): Salinity Description: Yield (L/s): 1.000	
Site Details			
Site Chosen By:			
		CountyParishCadastreForm A: CUMBERLANDMULGOA1//998482Licensed:Licensed:Licensed	

Region: 10 - Sydney South Coast	СМА Мар:	
River Basin: - Unknown Area/District:	Grid Zone:	Scale:
Elevation: 0.00 m (A.H.D.) Elevation Source: Unknown	Northing: 6262406.000 Easting: 286110.000	Latitude: 33°45'24.7"S Longitude: 150°41'26.4"E
GS Map: -	MGA Zone: 56	Coordinate Source: Unknown

GS Map: -


Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

Hole	Pipe	Component	Туре	From (m)	To (m)	Outside Diameter (mm)	 Interval	Details
1		Hole	Hole	0.00	8.00	0		Unknown
1	1	Casing	Concrete	0.00	0.00	1200		

*** End of GW103048 ***

Warning To Clients: This raw data has been supplied to the WaterNSW by drillers, licensees and other sources. WaterNSW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.



WaterNSW Work Summary

GW029710

Licence:	10WA112614	Licence Status:	CURRENT	
		Authorised Purpose(s): Intended Purpose(s):		
Work Type:	Well			
Work Status:				
Construct.Method:	Hand Dug			
Owner Type:	Private			
Commenced Date: Completion Date:		Final Depth: Drilled Depth:	7.90 m 7.90 m	
Contractor Name:	(None)			
Driller:				
Assistant Driller:				
Property:	N/A NSW	Standing Water Level (m):		
GWMA: GW Zone:	603 - SYDNEY BASIN -	Salinity Description: Yield (L/s):		
Site Details				
Site Chosen By:				
		County Form A: CUMBERLANI		Cadastre 90

		Licensed: CUMBERLAND	MULGOA	Whole Lot 25//752044
Region:	10 - Sydney South Coast	CMA Map: 9030-3N		
River Basin: Area/District:	212 - HAWKESBURY RIVER	Grid Zone:	Scale	:
Elevation: Elevation Source:	0.00 m (A.H.D.) (Unknown)	Northing: 6262724.000 Easting: 286046.000		: 33°45'14.3"S : 150°41'24.2"E

Coordinate Source: GD., ACC. MAP

GS Map: -

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

MGA Zone: 56

Hole	Pipe	Component	Туре	-	To (m)	Outside Diameter (mm)	 Interval	Details
1	1	Casing	Concrete Cylnder	-0.40	-0.40	1219		

Water Bearing Zones

From (m)	To (m)	Thickness (m)	WBZ Туре	S.W.L. (m)	D.D.L. (m)	(L/s)	Hole Depth (m)	Duration (hr)	Salinity (mg/L)
6	00 7.80	1.80	Unconsolidated	6.00		1.89			

Drillers Loa

	To (m)	Thickness (m)	Drillers Description	Geological Material	Comments
0.00	2.74	2.74	Loam Red	Loam	
2.74	7.92	5.18	Sand Gravel Water Supply	Sand	

Remarks

10/03/1981: 9 WORTH ST PENRITH (LOT 25)

*** End of GW029710 ***

Warning To Clients: This raw data has been supplied to the WaterNSW by drillers, licensees and other sources. WaterNSW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

WaterNSW Work Summary

GW101178

10WA112767	Licence Status:	CURRENT
		RECREATION (GROUNDWATER),INDUSTRIAL INDUSTRIAL, RECREATION (GROU
Bore		
Supply Obtained		
Rotary Air		
Private		
15/01/1998	Final Depth: Drilled Depth:	
INTERTEC DRILLING SERVICES		
Colin Leslie Barden		
PENRITH SHOWGROUND 127- 141 Station St PENRITH 2750 NSW - -	Standing Water Level (m): Salinity Description: Yield (L/s):	
	Bore Supply Obtained Rotary Air Private 15/01/1998 INTERTEC DRILLING SERVICES Colin Leslie Barden PENRITH SHOWGROUND 127- 141 Station St PENRITH 2750 NSW	Authorised Purpose(s): Intended Purpose(s): Bore Supply Obtained Rotary Air Private 15/01/1998 INTERTEC DRILLING SERVICES Colin Leslie Barden PENRITH SHOWGROUND 127- 141 Station St PENRITH 2750 NSW -

Site Details

Site Chosen By:

			County CUMBERLAND CUMBERLAND	Parish MULGOA MULGOA	Cadastre 1 998482 Whole Lot 12//1176987	
Region:	10 - Sydney South Coast	CMA Map:				
River Basin: - Unknown Area/District:		Grid Zone:		Scale:		
Elevation: Elevation Source:	0.00 m (A.H.D.) Unknown		6262566.000 285844.000		33°45'19.3"S 150°41'16.2"E	
GS Map:	-	MGA Zone:	56	Coordinate Source:	Unknown	

Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack; PC-Pressure Cemented; S-Sump; CE-Centralisers

Hole	Pipe	Component	Туре	From (m)	To (m)	Outside Diameter (mm)	Inside Diameter (mm)	Interval	Details
1		Hole	Hole	0.00	6.00	200			Rotary Air
1		Hole	Hole	6.00	11.20	168			Other
1		Annulus	Waterworn/Rounded	-0.80	11.20				Graded, Q:0.100m3
1	1	Casing	Pvc Class 12	-0.80	11.20	114			Seated on Bottom, Glued
1	1	Casing	Steel	-0.80	11.20	168	158		Seated on Bottom, Welded
1	1	Opening	Slots - Vertical	6.20	10.20	168		0	Oxy-Acetylene Slotted, Steel, SL: 100.0mm, A: 2.00mm
1	1	Opening	Screen	7.70	10.70	114		0	PVC Class 12, Glued, A: 0.40mm

Water Bearing Zones

- L		-	Thickness (m)	WBZ Туре	-	D.D.L. (m)	Yield (L/s)		Duration (hr)	Salinity (mg/L)
	6.00	10.50	4.50	Unknown	8.00		0.60	11.20	01:00:00	180.00

Drillers Log

From To Thick	kness Drillers Description	Geological Material	Comments	1		
Docuntipet/Sealibin@data75/2ternsw.com.au/wgen/users/8c5afec8fa9d42fc8fcf00a9d138538b/gw101178.agagpf_org.wsr.htm?1600657698676&160065 1/2 Version: 1, Version Date: 01/12/2020						

21/09/2020

https://realtimedata.waternsw.com.au/wgen/users/8c5afec8fa9d42fc8fcf00a9d138538b/gw101178.agagpf_org.wsr.htm?160065769...

(m)	(m)	(m)			
0.00	2.00	2.00	Sandy clay	Sandy Clay	
2.00	6.00	4.00	Grey sand	Sand	
6.00	10.50	4.50	Coarse gravel and cobbles (water bearing)	Gravel	
10.50	11.20	0.70	Dark grey shale and clay	Shale	

Remarks

15/01/1998: Form A Remarks:

Chlorine added on completion. 19/04/2001: PREVIOUS LIC NO: 10BL158273

22/01/2013: Nat Carling, 22-Jan-2013; Added rock type codes to driller's log & added missing information (based on existing data).

*** End of GW101178 ***

Warning To Clients: This raw data has been supplied to the WaterNSW by drillers, licensees and other sources. WaterNSW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

GENERAL NOTES:

- * THE POSITION OF FEATURES ARE INDICATIVE ONLY.
- SERVICES SHOWN HEREON HAVE BEEN LOCATED WHERE POSSIBLE BY FIELD SURVEY. PRIOR TO ANY EXCAVATION OR CONSTRUCTION ON THE SITE, THE RELEVANT AUTHORITY SHOULD BE CONTACTED FOR POSSIBLE LOCATION OF ANY OTHER SERVICES INCLUDING THOSE WHICH MAY BE UNDERGROUND.
- * INDICATES EXISTING SURFACE LEVEL.
- CONTOURS SHOWN DEPICT THE GENERAL TOPOGRAPHY. THEY DO NOT REPRESENT EXACT LEVELS OTHER THAN AT SPOT LEVELS SHOWN.
- RELATIONSHIP OF IMPROVEMENTS TO BOUNDARIES IS DIAGRAMMATIC ONLY. WHERE * OFFSETS ARE CRITICAL THEY SHOULD BE CONFIRMED BY FURTHER SURVEY
- THE TREE SIZES ARE APPROXIMATE ONLY. FURTHER FIELD INSPECTION SHOULD BE CARRIED * OUT WHERE TREE DETAILS ARE CONSIDERED TO CRITICALLY AFFECT DESIGN. THE TREE SIZES ARE SHOWN AS:- TRUNK DIAMETER/CANOPY SPREAD/HEIGHT
- * ORIGIN OF LEVELS: PM 12633 (SCIMS 14-12-2017)

Boundary NOTE:

The survey undertaken does not include a boundary redefinition & the current title system of the subject lots is Old System meaning there is a degree of uncertainty of the location of the boundaries.

In view of the uncertainty of the location of the boundaries as determined by the limitations of the survey requested and the age & the title system of the deposited plan we advise that only further survey would determined the true position of the boundaries to a standard suitable for acceptance of (a Real Property Application) at Land Registry Services.

Dimensions shown have been taken from the dimensions & adjoining plans, noted as "Survey" as per above.

Freeburn surveying recommends a plan of redefinition survey be prepared & lodged at Land Registry Services before any design and construction commences

Services NOTE:

* SERVICES SEARCH HAS BEEN UNDERTAKEN. THIS OFFICE HOLDS A COPY OF THAT SERVICES SEARCH. NUMEROUS AUTHORITY ASSETS EXIST WITHIN THE SURVEYED AREA. ALL CONSULTANTS SHOULD UNDERTAKE THEIR OWN SERVICES SEARCH. SURVEY HAS LOCATED VISIBLE SURFACE FILLINGS - NO POTHOLING OR EXCAVATION HAS BEEN UNDERTAKEN.

CAD NOTE:

THESE PLANS SHOULD BE READ IN CONJUNCTION WITH DIGITAL DATA ISSUED TO CLIENT. THE DIGITAL DATA CONTAINS NUMEROUS LAYERS OF INFORMATION WHICH ARE NOT SHOWN ON THESE PLANS FOR THE SAKE OF CLARITY.

STATION

STREET

BM on Kerb

RL 27.33 AHD

Approx Position 150mm Steel Gas main (Jemena Diagram)


Client: David Reeves & Jim Aitken MORSON GROUP

LEGEND

Hvdran

Project: PLAN OF DETAIL SURVEY, LEVELS & CONTOURS OVER LOTS 4 & 5 IN DP 112466 & LOT 6 DP 1003862 118-120 STATION STREET, PENRITH

Document Set ID: 9397752 Version: 1, Version Date: 01/12/2020



Edge

