

# Service protection report

**Joseph plumbing**

**supplier no: 873**

**Property Address:** 3 Valleyview Cres, Werrington Downs, NSW 2747

**Client:** (Nemco Design)

**PNum:** 14007291

*From the manhole centre to the left side boundary = 0.65 m  
From the manhole centre to the front boundary = 2.2 m  
Depth to invert = 1.45 m*

*The sewer crosses the back side fence at a distance to the left side fence = 2.35 m  
Depth to invert = 2.1 m  
Pipe type = 150 VC*

**Valleyview Cres**

7051

150 VC

25.7

4.4

150 VC

5.1

*The sewer crosses the back side fence at a distance to the right side fence = 12.2 m  
Depth to invert = 3 m  
Pipe type = 150 VC*

*From the manhole centre to the right side boundary = 0.9 m  
From the manhole centre to the rear boundary (measured along right side fence) = 0.8 m  
Depth to invert (to manhole lid) = 2.9 m  
Manhole lid is 0.7 m under ground level*

**Pipe size:** 150 mm

**Pipe type:** V.C.

**Strata:** Clay

**Asset Location method:** Electronic Pipe Locator/ Potholing/ Surveying/ Accessing structures

**Asset indicators:** Paint on fence

I, Housien Nasrallah of Joseph plumbing being accredited by Sydney Water to carry out service protection reports, certify that the information shown on this report is accurate and has been prepared in accordance with the relevant instructions.

Prepared by: Joseph plumbing

signature:

Date: 21/06/2018

**Housien.nasrallah@gmail.com**

**Mobile: 0410055075**

**Abn: 35134685108**