

# GETEX AIRBORNE ASBESTOS MONITORING REPORT

**Report Number:** 11538. 5 .AMON

**Date of Report:** 31/03/2021

**Date of Analysis:** 31/03/2021

**Client Company:** Penrith City Council

**Site:** 25-29 Chameleon Drive

PO Box 60

Erskine Park NSW 2759

PENRITH NSW 2751

**GETEX PTY LTD**

ABN 99 116 287 471

Unit 2, Building B, 64 Talavera Road  
MACQUARIE PARK NSW 2113

Ph: (02) 9889 2488  
Fax: (02) 9889 2499  
Email: help@getex.com.au  
Web: www.getex.com.au



**"Urgent Solutions To Urgent Problems"**

**24 Hours 7 Days**

**Removal Contractor:** N/A

**Test Method:** In accordance with NOHSC Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC: 3003 (2005)]

Sample Number	Sample Date	Sample Type	Monitor Location	Air Flow On (L/min)	Air Flow Off (L/min)	Air Flow Average (L/min)	Time On	Time Off	Total Time (min)	Field Count	Fibre Count	Conc. (fibres/mL)	Remarks
Blank	30/03/2021	7	N/A		N/A			N/A		100	0	N/A	
DRW 25	30/03/2021	1	On temporary fence - Southern corner of site	2.95	2.95	2.95	10:36	13:40	184	100	0	< 0.01	
DRW 26	30/03/2021	1	Centrally on south-western temporary fence opposite carpark	2.95	2.95	2.95	10:39	13:42	183	100	0	< 0.01	
DRW 27	30/03/2021	1	On temporary fence - Western corner of site	2.95	2.95	2.95	10:43	13:44	181	100	0	< 0.01	

**Sample Types:** 1 - Background 2 - Enclosure Set Up 3 - Removal/Treatment 4 - Enclosure Pull Down 5 - Clearance Monitoring 6 - Exposure Monitoring  
7 - Blank 8 - Bag Out / Waste Removal

**Note on Sampling:**

The above results only relate to the samples tested. This report confirms preliminary report \_\_\_\_\_ N/A

**Sampled by:** Chris Chen

**Counter Name:** Geronimo Abrot

**Counter Signature:** [Redacted]

**Approved Signatory Name:** Justin Thompson-Laing

**Approved Signatory:** [Redacted]

NATA Accredited Laboratory  
Number 15404:

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025 - Testing



This report shall not be reproduced except in full.

# GETEX AIRBORNE ASBESTOS MONITORING REPORT

Report Number: 11538. 5 .AMON

Date of Report: 31/03/2021

Date of Analysis: 31/03/2021

Client Company: Penrith City Council

Site: 25-29 Chameleon Drive

PO Box 60

Erskine Park NSW 2759

PENRITH NSW 2751

**GETEX PTY LTD**

ABN 99 116 287 471

Unit 2, Building B, 64 Talavera Road  
MACQUARIE PARK NSW 2113

Ph: (02) 9889 2488  
Fax: (02) 9889 2499  
Email: help@getex.com.au  
Web: www.getex.com.au



**"Urgent Solutions To Urgent Problems"**

**24 Hours 7 Days**

Removal Contractor: N/A

Test Method: In accordance with NOHSC Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres  
2nd Edition [NOHSC: 3003 (2005)]

Sample Number	Sample Date	Sample Type	Monitor Location	Air Flow On (L/min)	Air Flow Off (L/min)	Air Flow Average (L/min)	Time On	Time Off	Total Time (min)	Field Count	Fibre Count	Conc. (fibres/mL)	Remarks
Blank	30/03/2021	7	N/A			N/A		N/A		100	0	N/A	
DRW 28	30/03/2021	1	On temporary fence - North-western corner of site	2.95	2.95	2.95	10:47	13:45	178	100	0	< 0.01	
DRW 29	30/03/2021	1	On temporary fence - Adjacent 23 Chameleon Dr north-western corner boundary fence	2.95	2.95	2.95	10:50	13:47	177	100	1	< 0.01	
DRW 30	30/03/2021	1	Centrally on north-eastern boundary fence opposite dwelling	2.95	2.95	2.95	10:53	13:49	176	100	1	< 0.01	

Sample Types: 1 - Background 2 - Enclosure Set Up 3 - Removal/Treatment 4 - Enclosure Pull Down 5 - Clearance Monitoring 6 - Exposure Monitoring  
7 - Blank 8 - Bag Out / Waste Removal

**Note on Sampling:**

The above results only relate to the samples tested. This report confirms preliminary report \_\_\_\_\_ N/A

Sampled by: Chris Chen

Counter Name: Geronimo Abrot

Counter Signature:

Approved Signatory Name: Justin Thompson-Laing

Approved Signatory:

NATA Accredited Laboratory  
Number 15404:

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025 - Testing



This report shall not be reproduced except in full.

# GETEX AIRBORNE ASBESTOS MONITORING REPORT

**Report Number:** 11538 . 5 .AMON

**Date of Report:** 31/03/2021

**Date of Analysis:** 31/03/2021

**Client Company:** Penrith City Council

**Site:** 25-29 Chameleon Drive

PO Box 60

Erskine Park NSW 2759

PENRITH NSW 2751



**GETEX PTY LTD**

ABN 99 116 287 471

Unit 2, Building B, 64 Talavera Road  
MACQUARIE PARK NSW 2113

Ph: (02) 9889 2488  
Fax: (02) 9889 2499  
Email: help@getex.com.au  
Web: www.getex.com.au

**Removal Contractor:** N/A

**Test Method:** In accordance with NOHSC Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC: 3003 (2005)]

**"Urgent Solutions To Urgent Problems"**

**24 Hours 7 Days**

Sample Number	Sample Date	Sample Type	Monitor Location	Air Flow On (L/min)	Air Flow Off (L/min)	Air Flow Average (L/min)	Time On	Time Off	Total Time (min)	Field Count	Fibre Count	Conc. (fibres/mL)	Remarks
Blank	30/03/2021	7	N/A		N/A			N/A		100	0	N/A	
DRW 31	30/03/2021	1	On boundary fence - South-eastern corner of site	2.95	2.95	2.95	10:56	13:58	182	100	0	< 0.01	
DRW 32	30/03/2021	1	Centrally on south-east temporary fence opposite Chameleon Dr	2.95	2.95	2.95	10:59	13:51	172	100	0	< 0.01	

**Sample Types:** 1 - Background 2 - Enclosure Set Up 3 - Removal/Treatment 4 - Enclosure Pull Down 5 - Clearance Monitoring 6 - Exposure Monitoring  
7 - Blank 8 - Bag Out / Waste Removal

**Note on Sampling:**

The above results only relate to the samples tested. This report confirms preliminary report \_\_\_\_\_ N/A

**Sampled by:** Chris Chen

**Counter Name:** Geronimo Abrot

**Counter Signature:**

**Approved Signatory Name:** Justin Thompson-Laing

**Approved Signatory:**

NATA Accredited Laboratory  
Number 15404:

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025 - Testing



This report shall not be reproduced except in full.