

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	21/11/15
Signature of Surveyor	
B/A No.	
Lot No.	179
Street:	The Promenade
Client:	Firststyle Homes
Job No:	1121-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	27/6/15
Signature of Surveyor	<i>[Signature]</i>
B/A No.	
Lot No.	180
Street:	The Promenade
Client:	Firestyle burner
Job No:	1123-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	27/6/15
Signature of Surveyor	<i>[Signature]</i>
B/A No.	
Lot No.	181
Street:	The Promenade
Client:	Firstlye Homes
Job No:	1124-1.5

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date: <i>27/6/15</i>
Signature of Surveyor <i>[Signature]</i>
B/A No.
Lot No. <i>182</i>
Street: <i>The Promenade</i>
Client: <i>Firsttype Homes</i>
Job No: <i>1125-15</i>

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	21/6/15
Signature of Surveyor	
B/A No.	
Lot No.	184
Street:	The Promenade
Client:	Pistole Homes
Job No:	1127-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	21/6/15
Signature of Surveyor	
B/A No.	
Lot No.	184
Street:	The Promenade
Client:	Pistole Motors
Job No:	1127-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	27/11/15
Signature of Surveyor	<i>[Signature]</i>
B/A No.	
Lot No.	186
Street:	The promenade
Client:	Firststyle Homes
Job No:	1120-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	25/6/15
Signature of Surveyor	<i>[Signature]</i>
B/A No.	
Lot No.	188
Street:	The promenade
Client:	Fistale Farms
Job No:	1131-15

Note: Each damaged section must be indicated by a cross (X)


Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works

To: Council/Engineers Department

Any Kerb & Gutter: Yes No Damage: Yes No

Any Footpath: Yes No Damage: Yes No



Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	27/11/15
Signature of Surveyor	
B/A No.	
Lot No.	190
Street:	The promenade
Client:	First, k home
Job No:	1123-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	22/6/15
Signature of Surveyor	
B/A No.	
Lot No.	191
Street:	The Promenade
Client:	Firststyle Homes
Job No:	1134-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works

To: Council/Engineers Department


Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No

| Lot 192 |



Inspection Date:	27/6/15
Signature of Surveyor	<i>[Signature]</i>
B/A No.	
Lot No.	192
Street:	The promenade
Client:	FIRSTYK HOMES
Job No:	1135-15

Note: Each damaged section must be indicated by a cross (X)

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	27/6/15
Signature of Surveyor:	<i>[Signature]</i>
B/A No.	
Lot No.	193
Street:	The Promenade & Radcliffe Place
Client:	Firststyle Homes
Job No:	1136-15

Note: Each damaged section must be indicated by a cross (X)