


# Aspect Development & Survey

## Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works

To: Council/Engineers Department CLEVELAND LANE

Any Kerb & Gutter:     Yes     No                      Damage:     Yes     No  
 Any Footpath:         Yes     No                      Damage:     Yes     No



Inspection Date:	<u>20/11/14</u>
Signature of Surveyor:	
B/A No.	
Lot No.	<u>2346</u>
Street:	
Client:	
Job No:	<u>746-14</u>

*Note: Each damaged section must be indicated by a cross (X)*