

Aspect Development & Survey

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works


To: Council/Engineers Department

Any Kerb & Gutter: Yes No

Damage: Yes No

Any Footpath: Yes No

Damage: Yes No



Inspection Date:	20/11/14
Signature of Surveyor:	
B/A No.:	
Lot No.:	2228
Street:	
Client:	
Job No.:	768-14

Note: Each damaged section must be indicated by a cross (X)